

The AirLiner™ Wireless Slate Turns Off Unexpectedly



Applies to: The AirLiner™ wireless slate used with SMART Board™ software 9.5 for the Mac OS X operating system

Issue

Your AirLiner wireless slate turns off unexpectedly.

Cause

The battery status bubble no longer appears on the Mac OS X desktop when a connected AirLiner slate's battery is low. This is a known issue in SMART Board software 9.5 and will be addressed in a future software update.

Solution

Recharge the AirLiner slate's battery.

First Published: May 25, 2006

Last Updated: November 9, 2007

SMART Technologies
1207 – 11 Avenue SW, Suite 300
Calgary, AB T3C 0M5
CANADA



www.smarttech.com/support www.smarttech.com/contactsupport
Support +1.403.228.5940 or Toll Free 1.866.518.6791 (Canada/U.S.)

© 2006–2007 SMART Technologies ULC. All rights reserved. AirLiner, SMART Board, smarttech and the SMART logo are trademarks or registered trademarks of SMART Technologies ULC in the U.S. and/or other countries. All other third-party product and company names may be trademarks of their respective owners. US5448263; US6141000; US6326954; US6337681; US6741267; US6747636; US7151533; and CA2058219. Other patents pending. Contents are subject to change without notice. 11/2007.